



# Site Diagram



## On-site Sample Locations



Photos: 1 - 4  
Samples: X201,  
X201E, X301

Photo: 5  
Sample: X302

Digital Photographs



Bureau Id: 0998160003  
Photo No.: 1  
Photo Date: 1/12/2023  
Photo Time: 2:16:40 PM  
Direction: Northeast  
Taken By: Greg Kazmerski

Overview of impacted structure  
(Building 55)



Bureau Id: 0998160003  
Photo No.: 2  
Photo Date: 1/12/2023  
Photo Time: 2:32:36 PM  
Direction: Down  
Taken By: Greg Kazmerski

Area near Sample X201 / X301



Bureau Id: 0998160003  
Photo No.: 3  
Photo Date: 1/12/2023  
Photo Time: 2:36:06 PM  
Direction: Down  
Taken By: Greg Kazmerski

Area near X201 / X301



Bureau Id: 0998160003  
Photo No.: 4  
Photo Date: 1/12/2023  
Photo Time: 2:50:05 PM  
Direction: Northeast  
Taken By: Greg Kazmerski

Sample X201 / X301



Bureau Id: 0998160003  
Photo No.: 5  
Photo Date: 1/12/2023  
Photo Time: 3:48:14 PM  
Direction: South  
Taken By: Greg Kazmerski

Sample X302



Bureau Id: 0998160003  
Photo No.: 6  
Photo Date: 1/12/2023  
Photo Time: 4:17:33 PM  
Direction: South  
Taken By: Greg Kazmerski

Sample [REDACTED]